

ABSTRACT

A method of fabricating a blank mask, the method including: forming a light-shielding film on a light-transmissive substrate; and cleaning the light-shielding film with a cleaning solution, wherein in the cleaning, the light-shielding film has a thickness change of less than 5 nm.

5

(Fig. 1)